

# Download Bmw Zf Manual Transmission

137 thoughts on “ Everything about your ZF 6HP26, 6HP19, 6HP28 transmission issues ” Antonio November 18, 2014 at 1:03 am. Hello, great information.ZF 5HP30 Automatic Transmission Service How to change the transmission fluid and filter on a 1996 BMW 750iL. by Mike Burnett . Note: Refer to ZF\_5HP24\_Spare\_Parts.pdf and ZF\_5HP30\_Spare\_Parts.pdf for additional information on the fluid and filter changes procedures for the two different transmissions used in the e38.The 4HP22 is a four-speed automatic transmission from ZF Friedrichshafen AG for passenger cars with rear wheel drive or 4X4 layout. Introduced in 1980, it was produced through 2003, and has been used in a variety of cars from BMW, General Motors, Jaguar, Land Rover, Maserati, Peugeot, and Volvo.ZF Friedrichshafen AG, also known as ZF Group, originally Zahnradfabrik Friedrichshafen, and commonly abbreviated to ZF (ZF = "Zahnradfabrik" = "Gear Factory"), is a German car parts maker headquartered in Friedrichshafen, in the south-west German region of Baden-Württemberg.